

## THE COMMONWEALTH OF MASSACHUSETTS DEPARTMENT OF PUBLIC UTILITIES

MAURA T. HEALEY GOVERNOR

KIMBERLEY DRISCOLL LIEUTENANT GOVERNOR

REBECCA L. TEPPER SECRETARY OF ENERGY AND ENVIRONMENTAL AFFAIRS ONE SOUTH STATION BOSTON, MA 02110 (617) 305-3500 CECILE M. FRASER ACTING CHAIR

ROBERT E. HAYDEN COMMISSIONER

March 7, 2023

## VIA ELECTRONIC MAIL

Mr. Ronald Ester Chief Safety Officer MBTA Safety Department 185 Kneeland Street Boston, MA 02111

RE: Priority 1 (Red Conditions) Reporting to DPU

## **Immediate Action Notice**

Dear Mr. Ester,

On March 6, 2023 a Department of Public Utilities track engineer and I were present with an instructor and section repair person to conduct an independent review of track conditions and the MBTA's compliance with the agency safety plan. DPU walked the red line section of track between Ashmont and Savin Hills on the southbound track. As a result of this inspection, the current version of the MBTA rule book and special orders the DPU identified a condition that requires an immediate corrective action.

Therefore, the DPU directs you to take the following actions:

- 1. MBTA will provide the DPU with a daily report of priority 1 (red conditions) that are listed as both open and pending within the E&M on the Red Line.
- 2. Upon completion of any priority 1 (red) condition (on the red line), MBTA will provide DPU with notification of what corrective action was taken.

- 3. MBTA will report any new priority 1 (red conditions) identified by track inspections to the DPU for tracking.
- 4. MBTA within 24 hours will provide DPU with a corrective action plan that will identify the actions needed and a strategy for hazard/ risk analysis for prioritizing repair work.

Please contact me if you have any questions,

Sincerely,

Robert N. Hanson

Director Rail Transit Safety

cc:

- J. Gonneville, MBTA
- E. Stoothoff, MBTA
- R. Ester, MBTA
- S. Culp, MBTA
- P. Roman, DPU
- D Carvalho, DPU